

END SENT
IN-37-CR
104400
52P.

STUDY OF FREE-PISTON STIRLING ENGINE

DRIVEN LINEAR ALTERNATORS

(NASA-CR-181425) STUDY OF FREE-PISTON
STIRLING ENGINE DRIVEN LINEAR ALTERNATORS
Final Report (Kentucky Univ.) 52 p Avail:
NTIS HC A04/MF A01 CSCL 13I

N88-10355

Unclas
G3/37 0104400

S. A. Nasar

and

C. Chen

Electrical Engineering Department
University of Kentucky
Lexington, KY 40506-0046

Prepared for
NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
Lewis Research Center
Cleveland, Ohio
Under Grant No. NAG3-722

July 31, 1987

ACKNOWLEDGMENTS

We are indebted to NASA Lewis Research Center for Grant No. NAG3-722 which afforded the work reported here. We also wish to express our gratitude to Gene E. Schwarze, Technical Officer, for his guidance during the course of this research.

ABSTRACT

In this report, the analysis, design and operation of single-phase, single-slot tubular permanent magnet linear alternator is presented. The study includes the no-load and on-load magnetic field investigation, permanent magnet's leakage field analysis, parameter identification, design guidelines and an optimal design of a permanent magnet linear alternator. For analysis of the magnetic field, a simplified magnetic circuit is utilized. The analysis accounts for saturation, leakage and armature reaction.

List of Principal Symbols

B	Flux density, T
f_m	Frequency of the alternator, Hz
H	Magnetic field intensity, A/m
I	Demagnetizing component (of armature reaction) of stator (or primary) current, A
I_1	Stator (or primary) current, A
k	A coefficient
k_{fu}	Fill factor
k_{sm}	Leakage coefficient of permanent magnet.
L_σ	Leakage inductance, H
L_m	Mutual inductance, H
L_{me}	Equivalent mutual inductance, H
R_a	Stator (or primary) winding resistance, Ω
R_L	Load resistance, Ω
W	Weight, lb.
W_1	Stator (or primary) winding turns, turn
Z_i	Iron loss, watt
Z_c	Copper loss, watt
ϕ	Flux, Wb.
λ	Flux linkage, Wb-turn
ω	Electrical angular frequency, R/S

Subscripts

gav	Average value in airgap
pch	Average value in the horizontal part of flux path in plunger back iron.
pcv	Average value in the vertical part of flux path in plunger back iron.
sp	Average value in stator pole shoes.
scv	Average value in the vertical part of stator back iron.
sch	Average value in the horizontal part of stator back iron.
g	airgap
p	plunger
s	stator
m	magnet
v	vertical
h	horizontal
c	core (back iron).

TABLE OF CONTENTS

CHAPTER 1	INTRODUCTION	1
CHAPTER 2	THE FIELD OF A TUBULAR PM LINEAR ALTERNATOR	3
CHAPTER 3	THE LEAKAGE FIELD OF PERMANENT MAGNETS IN A PM LINEAR ALTERNATOR	16
CHAPTER 4	PARAMETERS OF PM LINEAR ALTERNATOR	21
CHAPTER 5	DESIGN OF A TUBULAR PM LINEAR ALTERNATOR	29
CHAPTER 6	OPTIMAL DESIGN OF A PM LINEAR ALTERNATOR	37
CHAPTER 7	CONCLUSIONS	43
	REFERENCES	43
	APPENDIX I	44

CHAPTER 1

INTRODUCTION

Because it is a self-starting, quiet vibration-free and highly reliable device, the free-piston Stirling engine (FPSE) has recently received considerable attention. The FPSE is a strong candidate as a prime mover to drive a linear alternator in space power stations. The FPSE may use solar energy or nuclear energy as the source and can perform in any orientation—vertical, horizontal, inclined or upside down. For coupling with the FPSE, the linear alternator (LA) is most suited because of its simple structure and high efficiency of direct coupling. Fig. 1-1 shows a 5 kW free piston Stirling engine—linear alternator unit.

According to the method of excitation the linear alternators may be: (i) field-excited, with moving diodes; (ii) inductor or reluctance type, having both armature and field windings on the primary or (iii) permanent magnet (PM) excited. The PM linear alternator does not need any exciting winding and exciting power supply, so that it is simpler more reliable and lighter than the field-excited or reluctance-type linear alternator. Hence the PM linear alternator is considered more suitable for space power applications.

Past work on PM linear alternator is as follows:

- (i) Primitive PM linear alternators are presented in [1], [2] and [3].
- (ii) References [4] and [5] discuss the fundamental equations and basic design guidelines of a PM linear alternator.
- (iii) Reference [6] gives one design of PM linear alternator, but the design is not optimal for either the ratio of power to weight of the alternator or the efficiency of the alternator.

It is fair to say that the above does not reflect adequate analysis and design of PM linear alternators. The present work consists of the field analysis, parameter identification, design guideline and optimal design of PM linear alternators.

The following discussion is for the single-phase, single-slot tubular linear alternator. But the results can be extended to multi-phase and multi-slot tubular linear alternators.

ORIGINAL PAGE IS
OF POOR QUALITY




Figure 1-1 A five kW linear alternator (dimensions in cm).

CHAPTER 2

THE FIELD OF A TUBULAR PM LINEAR ALTERNATOR

2.1. Configuration of Single-Phase Single-Slot Tubular PM Linear Alternator

A single-phase single-slot tubular PM linear alternator is shown in Fig. 2-1, which has four pieces of magnets mounted on the plunger. The circular stator coils are embedded in stator slot. The plunger reciprocates with the stroke length:

$$\ell_{stroke} = \tau_m \quad (2-1)$$

The flux ϕ of permanent magnets in the airgap varies almost linearly with the position of the plunger, as shown in Fig. 2-2. If the plunger moves with a sinusoidal speed, a sinusoidal voltage will be induced in the stator winding. The flux of the permanent magnets has a maximum value at the ends of the plunger stroke.

2.2. Basic Equations of Magnetic Field and Demagnetization Curve of Permanent Magnet

Two very useful laws for electromagnetic field analysis are Ampere's Law and continuity of flux. Let there be n parts in a magnetic loop, then by the Ampere's Law:

$$WI = \sum_{i=1}^n H_i \ell_i \quad (2-2)$$

Continuity of flux requires that

$$\phi_1 = \phi_2 = \dots = \phi_n \quad (2-3)$$

In (2-2) and (2-3) W is the coil turns linking the magnetic loop, I is the current in the coil, H_i , ϕ_i , ℓ_i are field intensity, flux and length of part i of the magnetic loop respectively, $i=1,2,\dots,n$.

Let TASCORE 27 be the permanent magnet material used in the linear alternator for which the demagnetization curve is shown in Fig. 2-3. It may be seen that the demagnetization curve of TASCORE 27 is almost a linear curve and may be described approximately by:

$$H_m = H_c \left(1 - \frac{B_m}{B_r}\right) \quad (2-4)$$

or

$$B_m = B_r \left(1 - \frac{H_m}{H_c}\right) \quad (2-5)$$




Figure 2-1 Linear alternator geometry.




Figure 2-2 Flux variation with plunger position.

ORIGINAL PAGE IS
OF POOR QUALITY




Figure 2-3 Demagnetizing curve.

2.3. Procedure to Calculate No Load Field

The dimensions shown in Fig. 2-1 have the following relationships:

$$D_m = D_i - 2g - h_m \quad (2-6)$$

$$D_{p1} = D_i - 2g - 2h_m - b_p \quad (2-7)$$

$$D_{p2} = D_i - 2g - 2h_m - \frac{1}{2} b_p \quad (2-8)$$

$$D_s = D_i + h_1 \quad (2-9)$$

$$D_{t1} = D_i + 2h_1 + h_2 + \frac{1}{2} b_b \quad (2-10)$$

$$D_{t2} = D_i + 2h_1 + 2h_2 + b_b \quad (2-11)$$

$$b = b_{s2} + b_t \quad (2-12)$$

The magnetic loop in Fig. 2-1 is divided into several sections. If it is assumed that the field is constant in each section, and by applying Ampere's Law to the path ABCDEFA, we obtain:

$$\begin{aligned} H_{sch} b + H_{scv}(2h_2 + b_b) + H_{sp} 2h_1 + H_{gav} 2g + H_{pcv} b_p \\ + H_{pch} b + H_m 2h_m = 0 \end{aligned} \quad (2-13)$$

or

$$\begin{aligned} H_m = - \frac{1}{2h_m} \left[H_{sch} b + H_{scv}(2h_2 + b_b) + H_{sp} 2h_1 + H_{gav} 2g \right. \\ \left. + H_{pcv} b_p + H_{pch} b \right] \end{aligned} \quad (2-14)$$

It will be shown in the next chapter that the leakage flux of permanent magnet is not a constant and can be expressed as:

$$\phi_\sigma = -kH_m = -kH_c \left(1 - \frac{B_m}{B_r}\right) \quad (2-15)$$

where k is a constant determined by the dimensions of the PM alternator. Continuity of flux (Fig. 2-4) yields:

$$\tau_m D_m B_m + kH_c \left(1 - \frac{B_m}{B_r}\right) = \frac{\tau + \tau_m}{2} (D_i - g) B_{gav} \quad (2-16)$$

$$\frac{\tau + \tau_m}{2} (D_i - g) B_{gav} = \frac{1}{2} (\tau + b_t) D_s B_{sp} \quad (2-17)$$

$$\frac{1}{2} (\tau + b_t) D_s B_{sp} = b_t D_{t1} B_{scv} \quad (2-18)$$

$$b_t D_{t1} B_{scv} = b_t D_{t2} B_{sch} \quad (2-19)$$

$$D_m B_m = D_{p2} B_{pcv} \quad (2-20)$$

$$\tau_m D_{p2} B_{pcv} = b_p D_{p1} B_{pch} \quad (2-21)$$

The saturation curve of the core material (M-19) is shown in Fig. 2-5. The algorithm for the determination of the field of the permanent magnet is as follows:




Figure 2-4 PM flux paths and continuity of flux.




Figure 2-5 B-H curves of selected soft magnetic materials.

- (i) Choose a value of H_{m0} on the demagnetization curve and an accuracy criterion ϵ .
- (ii) Find B_{m0} from (2-5).
- (iii) Find B in every part of the magnetic circuit with B_{m0} and (2-16) through (2-21).
- (iv) Determine H for each B from the B-H curve (Fig. 2-5).
- (v) Determine $H_{gap} = B_{gap}/\mu_o$ for the airgap.
- (vi) Calculate H_{m1} from (2-14).
- (vii) If $|H_{m0} - H_{m1}| \leq \epsilon$, stop calculations. The field due to this H_{m0} is the field of the permanent magnet.
- (viii) If $|H_{m0} - H_{m1}| > \epsilon$, choose $\frac{1}{2} (H_{m0} + H_{m1})$ as a new H_{m0} and return to stop (ii).

2.4. Field of a Linear Alternator on Load

The flux distribution in a linear alternator is shown in Fig. 2-6, where ϕ_1 denotes the mutual flux due to the permanent magnet, ϕ_2 the mutual flux due to the stator mmf, $\phi = \phi_1 - \phi_2$ the net mutual flux and ϕ_o the leakage flux due to permanent magnet. For ease of calculation, certain cross-sections are defined as follows. These cross-sections are denoted by S with subscripts,

$$S_{g1} = \pi (D_i - g) \frac{1}{2} (\tau + \tau_m) \quad (2-22)$$

$$S_{g11} = \pi (D_i - g) \left[\tau + 2(g + g_m) \frac{g/2}{g + h_m} \right] = \pi (D_i - g)(\tau + g) \quad (2-23)$$

$$S_{g2} = \pi (D_i - g - h_m)(\tau + g + h_m) \quad (2-24)$$

$$S_{g3} = \pi (D_i - 2g - h_m)(\tau + 2g + h_m) \quad (2-25)$$

$$S_{g3m} = \pi (D_i - 2g - h_m) \tau_m \quad (2-26)$$

$$S_{tp} = \pi (D_i + h_1) \frac{1}{2} (\tau + b_t) \quad (2-27)$$

$$S_{scs} = \pi (D_i + 2h_1 + h_2 + \frac{1}{2} b_b) b_t \quad (2-28)$$

$$S_{sch} = \pi (D_i + 2h_1 + 2h_2 + b_b) b_b \quad (2-29)$$

$$S_{pcs} = \pi (D_i - 2g - 2h_m - \frac{1}{2} b_p)(\tau + 2g + 2h_m) \quad (2-30)$$

$$S_{pch} = \pi (D_i - 2g - 2h_m - b_p) b_p \quad (2-31)$$

Let ϕ_m denote the flux due to the permanent magnet within the permanent magnets. Then:

$$\phi_m = \phi_o + \phi_1 \quad (2-32)$$

and in the permanent magnet:

$$B_m = \frac{\phi_m}{S_{g3m}} - \frac{\phi_2}{S_{g3}} \quad (2-33)$$

In the airgap:

$$\frac{\phi_2}{S_{g2}\mu_o} (g + h_m) = -H_m h_m - \left(\frac{\phi_1}{S_{g1}} - \frac{\phi_2}{S_{g11}} \right) \frac{g}{\mu_o} \quad (2-34)$$




Figure 2-6 Fluxes in a LA.

In the iron portion of stator, total flux

$$\phi = \phi_1 - \phi_2 \quad (2-35)$$

$$B_{sp} = \frac{\phi}{S_{sp}} \quad (2-36)$$

$$B_{scv} = \frac{\phi}{S_{scv}} \quad (2-37)$$

$$B_{sch} = \frac{\phi}{S_{sch}} \quad (2-38)$$

In the iron portion of the plunger:

$$B_{pcv} = \frac{\phi_m - \phi_2}{S_{pcv}} \quad (2-39)$$

$$B_{pch} = \frac{\phi_m - \phi_2}{S_{pch}} \quad (2-40)$$

If ϕ_1 , ϕ_2 and ϕ_σ are known, flux densities in every portion of the iron can be obtained from (2-32) and (2-35)-(2-40). For the corresponding flux density, the field intensity can be found from the magnetization curve of the core material.

Let:

$$F_m = 2H_{sp}h_1 + 2H_{scv}(h_2 + \frac{1}{2}b_b) + H_{sch}b + 2H_{pcv}(\frac{1}{2}b_p) + H_{pch}b \quad (2-41)$$

By Ampere's Law:

$$\frac{\phi_2}{\phi_1 - \phi_2} F_m + \frac{2\phi_2}{S_{g2}\mu_o} (g + h_m) = W_1 I \quad (2-42)$$

From Eq. (2-4), (2-15), (2-32) and (2-33):

$$H_m = H_c - \frac{H_c}{B_r} \left[\frac{\phi_1 - kH_m}{S_{g3m}} - \frac{\phi_2}{S_{g3}} \right] \quad (2-43)$$

or,

$$\left[1 - \frac{kH_c}{B_r S_{g3m}} \right] H_m = H_c - \frac{H_c \phi_1}{B_r S_{g3m}} + \frac{H_c \phi_2}{B_r S_{g3}} \quad (2-44)$$

Let

$$d = 1 - \frac{kH_c}{B_r S_{g3m}} \quad (2-45)$$

Equation (2-44) becomes:

$$dH_m = H_c - \frac{H_c \phi_1}{B_r S_{g3m}} + \frac{H_c \phi_2}{B_r S_{g3}} \quad (2-46)$$

and

$$\phi_1 = \left[(H_c - dH_m) \frac{B_r}{H_c} + \frac{\phi_2}{S_{g3}} \right] S_{g3m} \quad (2-47)$$

Substituting (2-47) into (2-34) yields:

$$\frac{\phi_2}{s_{g2}\mu_o} (g + h_m) = -H_m h_m - [(H_c - dH_m) \frac{B_r}{H_c} + \frac{\phi_2}{S_{g3}}] \frac{S_{g3m}g}{S_{g1}\mu_o} + \frac{\phi_2 g}{S_{g11}\mu_o} \quad (2-48)$$

Or,

$$\phi_2 = \frac{-\frac{B_r S_{g3m}g}{S_{g1}}}{\frac{g + h_m}{S_{g2}} + \frac{S_{g3m}g}{S_{g1}S_{g3}} - \frac{g}{S_{g11}}} - \frac{\mu_o h_m - \frac{dB_r S_{g3m}g}{H_c S_{g1}}}{\frac{g + h_m}{S_{g2}} + \frac{S_{g3m}g}{S_{g1}S_{g3}} - \frac{g}{S_{g11}}} H_m \quad (2-49)$$

Let:

$$a = \frac{-\frac{B_r S_{g3m}g}{S_{g1}}}{\frac{g + h_m}{S_{g2}} + \frac{S_{g3m}g}{S_{g1}S_{g3}} - \frac{g}{S_{g11}}} \quad (2-50)$$

and

$$c = -\frac{\mu_o h_m - \frac{dB_r S_{g3m}g}{H_c S_{g1}}}{\frac{g + h_m}{S_{g2}} + \frac{S_{g3m}g}{S_{g1}S_{g3}} - \frac{g}{S_{g11}}} \quad (2-51)$$

Now

$$\phi_2 = a + cH_m \quad (2-52)$$

Substituting (2-52) into (2-42) gives:

$$\frac{\phi_2}{\phi_1 - \phi_2} F_m + \frac{2(g + h_m)}{S_{g2}\mu_o} (a + cH_m) = W_1 I \quad (2-53)$$

$$H_m = \frac{1}{c} [-\frac{\phi_2}{\phi_1 - \phi_2} F_m + W_1 I] \frac{S_{g2}\mu_o}{2(g + h_m)} - a \quad (2-54)$$

To find the field of the linear alternator, choose (or guess) an initial value H_{mo} (of H_m). From (2-52), (2-47), (2-15), (2-32) and (2-35)-(2-40), the ϕ_2 , ϕ_1 , ϕ_o and the flux densities in all parts of iron corresponding to H_{mo} can be found. Another value of H_m is obtained by the magnetization curve of iron and Eq. (2-41) and (2-54). After a few iterations exact values of H_m and the fluxes are obtained.

2.5. An Example

A single-slot single-phase tubular PM linear alternator has the configuration shown in Fig. 2-1 and has the following dimensions and parameters:

$$\begin{aligned} \tau &= 1.2''; \tau_m = 1.0''; h_1 = 0.2''; h_2 = 0.8''; g = 0.036''; \\ h_m &= 0.46''; b_t = 0.5''; b_b = 0.45''; b_p = 0.7''; b_{s2} = 3.44''; \\ D_i &= 11''; B_r = 1.07 \text{ T}; H_c = -770.305 \text{ kA/m}; W_1 = 21 \text{ turns} \end{aligned}$$

By the calculating algorithm in section 2.3, the no load field of the alternator is calculated. The B and H in every part of the machine are:

$$B_m = 0.97242 \text{ T} \quad H_m = -70251.93000 \text{ A/m}$$

$$\begin{array}{ll} B_{sp} = 0.93418 \text{ T} & H_{sp} = 81.77248 \text{ A/m} \\ B_{scv} = 1.43153 \text{ T} & H_{scv} = 973.84080 \text{ A/m} \\ B_{sch} = 1.46938 \text{ T} & H_{sch} = 1698.5440 \text{ A/m} \\ B_{pcv} = 1.05397 \text{ T} & H_{pcv} = 100.79380 \text{ A/m} \\ B_{pch} = 1.56229 \text{ T} & H_{pch} = 3477.81500 \text{ A/m} \\ B_{gav} = 0.73740 \text{ T} & H_{gav} = 585241.40000 \text{ A/m} \end{array}$$

The mutual flux produced by PM is:

$$\phi = 0.01817 \text{ Wb}$$

The leakage coefficient of PM is:

$$k_{\sigma m} = 1 + \frac{\phi_{\sigma}}{\phi} = 1.1446$$

When the stator current $I_1 = 209.3 \text{ A}$ and $\theta = 45^\circ$ (shown in Fig. 2-7). The demagnetizing component of the stator current is:

$$I = I_1 \sin \theta = 209.3 \times \sin 45^\circ = 148 \text{ A}$$

By the formulas given in section 2.4, the field is:

$$\begin{array}{ll} B_m = 0.85001 \text{ T} & H_m = -158371.40000 \text{ A/m} \\ B_{sp} = 0.50827 \text{ T} & H_{sp} = 40.57893 \text{ A/m} \\ B_{scv} = 0.77887 \text{ T} & H_{scv} = 63.09837 \text{ A/m} \\ B_{sch} = 0.79946 \text{ T} & H_{sch} = 64.95149 \text{ A/m} \\ B_{pcv} = 0.80115 \text{ T} & H_{pcv} = 65.14345 \text{ A/m} \\ B_{pch} = 1.18753 \text{ T} & H_{pch} = 127.50650 \text{ A/m} \end{array}$$

The mutual flux due to PM is:

$$\phi_1 = 0.01549 \text{ Wb}$$

The mutual flux due to the current I is:

$$\phi_2 = 0.00561 \text{ Wb}$$

Net mutual flux:

$$\phi = \phi_1 - \phi_2 = 0.00988 \text{ Wb}$$

The leakage coefficient of PM is:

$$k_{\sigma m} = 1 + \frac{\phi_{\sigma}}{\phi} = 1.3822$$

The coefficient $k_{\sigma m}$ on load is larger than that for no load. The reason is that the magnitude of H_m increases with an increase in I.




Figure 2-7 The phase relation between E_o and I_1 .

CHAPTER 3

THE LEAKAGE FIELD OF PERMANENT MAGNETS IN A PM LINEAR ALTERNATOR

The leakage of the permanent magnets in a tubular PM linear alternator is shown in Fig. 3-1. Here the symmetrical line of a permanent magnet coincides with that of the stator teeth. For other positions of the permanent magnets the leakage field may be found in a way similar to the following. The field shown in Fig. 3-1 is only in the vicinity of a stator pole. The entire region of the field is divided into a number of sub-regions as shown. Flux calculations are made for these sub-regions.

In the flux calculations, the following conditions are assumed:

- In the sub-region ABCDA, the fluxes are perpendicular to AB and CD.
- In the sub-region BCGFEB, the flux pathes are semi-circles with different diameters and the center of those circles is the middle point between B and C.
- In the sub-region HIJKH, the flux pathes are quarter circles with center at point H.
- In the sub-region IJKPOMLI, the flux pathes are composed by quarter circles with center at point H and quarter circles with center at point K.

With the above assumption, in sub-region ABCD:

$$F_m = -H_m h \quad (3-1)$$

$$\begin{aligned} d\phi_{\sigma 1} &= \frac{F_m}{\frac{g_m/2}{\mu_o \pi (D_i - 2g - 2h_m + 2h) dh}} \\ &= \frac{-2H_m \mu_o \pi (D_i - 2g - 2h_m + 2h) h}{g_m} dh \end{aligned} \quad (3-2)$$

$$\begin{aligned} \phi_{\sigma 1} &= \int_0^{h_m} d\phi_{\sigma 1} \\ &= \int_0^{h_m} \frac{-2H_m \mu_o \pi (D_i - 2g - 2h_m + 2h) h}{g_m} dh \\ &= -\frac{H_m \mu_o \pi}{g_m} [(D_i - 2g - 2h_m) h_m^2 + \frac{4}{3} h_m^3] \end{aligned} \quad (3-3)$$

In sub-region BCGFEB:

$$r_1 = \sqrt{g^2 + [\frac{1}{2} (r_m + g_m - r)]^2} \quad (3-4)$$

$$F_m = -2H_m h_m \quad (3-5)$$

The reluctance on a flux path with width dr is:

$$dR_2 = \frac{\pi r}{\pi (D_i - g) \mu_o dr} = \frac{r}{\mu_o (D_i - g) dr} \quad (3-6)$$




Figure 3-1 Leakage field of the permanent magnets.

where $D_i - g$ is the average diameter of the cross-section of the flux path.

The infinitesimal flux over the path is:

$$d\phi_{\sigma 2} = \frac{F_m}{dR_2} = -2 \mu_o H_m h_m (D_i - g) \frac{dr}{r} \quad (3-7)$$

$$\begin{aligned} \phi_{\sigma 2} &= \int_{g_m/2}^{r_1} d\phi_{\sigma 2} \\ &= -2H_m \mu_o h_m (D_i - g) \ln \frac{2r_1}{g_m} \end{aligned} \quad (3-8)$$

In the sub-region HIJKH:

$$F_m = -H_m h \quad (3-9)$$

$$dR_3 = \frac{\frac{\pi h}{2}}{\pi(D_i - 2g - h_m) \mu_o dh} = \frac{h}{2(D_i - 2g - h_m) \mu_o dh} \quad (3-10)$$

where $D_i - 2g - h_m$ is the average diameter of cross-section of the flux path.

$$d\phi_{\sigma 3} = \frac{F_m}{dR_3} = -2H_m \mu_o (D_i - 2g - h_m) dh \quad (3-11)$$

or

$$\begin{aligned} \phi_{\sigma 3} &= \int_0^{h_m} d\phi_{\sigma 3} \\ &= -2H_m \mu_o (D_i - 2g - h_m) h_m \end{aligned} \quad (3-12)$$

In the sub-region of LMOPKJL:

$$\begin{aligned} F_m &= -H_m h_m \\ dR_4 &= \frac{\frac{1}{2} \pi (h_m + h) + \frac{1}{2} \pi h}{\pi(D_i - g - h_m) \mu_o dh} \\ &= \frac{h_m + 2h}{2(D_i - g - h_m) \mu_o dh} \end{aligned} \quad (3-13)$$

$$d\phi_{\sigma 4} = \frac{F_m}{dR_4} = \frac{-2H_m \mu_o (D_i - g - h_m) h_m}{h_m + 2h} dh \quad (3-14)$$

$$\begin{aligned} \phi_{\sigma 4} &= \int_0^g d\phi_{\sigma 4} \\ &= -H_m \mu_o (D_i - g - h_m) \ln \left(\frac{h_m + 2g}{h_m} \right) h_m \end{aligned} \quad (3-15)$$

Total leakage flux:

$$\phi_{\sigma} = \phi_{\sigma 1} + \phi_{\sigma 2} + \phi_{\sigma 3} + \phi_{\sigma 4}$$

$$= -H_m \mu_o \left\{ \frac{\pi}{g_m} \left[(D_i - 2g - 2h_m)h_m + \frac{4}{3} h_m^2 \right] + 2(D_i - g) \ln \frac{2r_1}{g_m} \right. \\ \left. + 2(D_i - 2g - h_m) + (D_i - g - h_m) \ln \left(\frac{h_m + 2g}{h_m} \right) \right\} h_m \quad (3-16)$$

where r_1 is given in (3-4).

The Eq. (3-16) may be rewritten as:

$$\phi_o = -KH_m \quad (3-17)$$

where

$$K = \mu_o \left\{ \frac{\pi}{g_m} \left[(D_i - 2g - 2h_m)h_m + \frac{4}{3} h_m^2 \right] + 2(D_i - g) \ln \frac{2r_1}{g_m} \right. \\ \left. + 2(D_i - 2g - h_m) + (D_i - g - h_m) \ln \left(\frac{h_m + 2g}{h_m} \right) \right\} h_m \quad (3-18)$$

It is obvious that K is dependent on the configuration of the alternator. The flux ϕ_m in the permanent magnet is given by:

$$\phi_m = \pi (D_i - 2g - h_m) \tau_m B_m \quad (3-19)$$

Combining (3-17), (3-19) and (2-4) yields:

$$\phi_o = -K(H_c - \frac{H_c}{B_r} B_m) \\ = -K H_c + K \frac{H_c}{B_r} \frac{1}{\pi(D_i - 2g - h_m) \tau_m} \phi_m \quad (3-20)$$

Equation (3-20) shows that the leakage flux decreases linearly with B_m (or ϕ_m). This happens because ϕ_o is directly proportional to H_m , which decreases linearly with B_m . The conclusion is that after the dimensions of the linear alternator have been decided, to reduce leakage flux B_m has to be chosen as high as possible.

The above analysis may be used to calculate the leakage coefficient of the linear alternator. By definition the leakage coefficient is:

$$k_{om} = \frac{\phi_m}{\phi_m - \phi_o} \quad (3-21)$$

From (3-20):

$$k_{om} = \frac{\phi_m}{\phi_m + KH_c - K \frac{H_c}{B_r} \frac{1}{\pi(D_i - 2g - h_m) \tau_m} \phi_m} \\ = \frac{1}{1 + K H_c \left(\frac{1}{\phi_m} - \frac{1}{B_r \pi (D_i - 2g - h_m) \tau_m} \right)} \quad (3-22)$$

Defining:

$$k_B = \frac{B_m}{B_r} \quad (3-23)$$

and substituting (3-19), (3-23) into (3-22) yields:

$$k_{\sigma m} = \frac{1}{1 + kH_c(1 - k_B) \frac{1}{\phi_m}} \quad (3-24)$$

Since H_c is negative, when B_m approaches B_r , i.e. k_B approaches 1, $k_{\sigma m}$ decreases to the limit 1. If B_m decreases, because ϕ_m will decrease with B_m , the second term in the denominator of (3-24) will increase rapidly. Thus $k_{\sigma m}$ will also increase rapidly.

CHAPTER 4

PARAMETERS OF PM LINEAR ALTERNATOR

The three important electrical parameters of a single-phase PM linear alternator are: leakage inductance, magnetizing inductance and resistance of the stator winding. The methods and formulas to find the three parameters are presented as follows.

4.1. Determination of Slot Leakage Inductance

The shape and the dimensions of the slot of a tubular single-phase single-slot tubular PM linear alternator are shown in Fig. 4-1. The winding in the slot has W_1 turns. The slot is divided into two regions—ABCF and CDEF as shown in Fig. 4-1. Let the current in the winding be I_1 .

For calculating the slot leakage inductance, the following assumptions are made:

- The current density in the coil is uniform.
- Iron around the slot has a much larger permeability than that of air.
- The leakage flux in the slot is parallel to the bottom of the slot.

In region ABCF, over a depth dx , the infinitesimal flux linkage is:

$$d\lambda_1 = (W_1 \frac{x}{h_2})^2 \pi(D_o - 2x) \frac{\mu_o I}{b_{s2}} dx \quad (4-1)$$

The total flux linkage in the region ABCF becomes:

$$\begin{aligned} \lambda_1 &= \int_0^{h_2} d\lambda_1 = \frac{\mu_o \pi I_1 W_1^2}{b_{s2}} \int_0^{h_2} (\frac{x}{h_2})^2 (D - 2x) dx \\ &= \frac{\mu_o \pi I_1 W_1^2}{b_{s2}} (\frac{1}{3} D_o h_2 - \frac{1}{2} h_2^2) \end{aligned} \quad (4-2)$$

For the region CDEF, the approximate equivalent slot width is $\frac{1}{2} (b_{s1} + b_{s2})$. Thus:

$$d\lambda_2 = \mu_o \pi I_1 W_1^2 (\frac{2}{b_{s1} + b_{s2}}) (D_i + 2y) dy \quad (4-3)$$

$$\begin{aligned} \lambda_2 &= \int_0^{h_1} d\lambda_2 = \mu_o \pi I_1 W_1^2 \frac{2}{b_{s1} + b_{s2}} \int_0^{h_1} (D_i + 2y) dy \\ &= \mu_o \pi I_1 W_1^2 \frac{2}{b_{s1} + b_{s2}} (D_i h_1 + h_1^2) \end{aligned} \quad (4-4)$$

Total slot leakage flux linkage is:

$$\lambda_{s\sigma} = \lambda_1 + \lambda_2 \quad (4-5)$$

Hence, from (4-2), (4-4) and (4-5), the slot leakage inductance is:

$$L_{s\sigma} = \frac{\lambda_{s\sigma}}{I_1} = \mu_o \pi W_1^2 (\frac{D_o h_2}{3 b_{s2}} - \frac{h_2^2}{2 b_{s2}} + \frac{2 D_i h_1}{b_{s1} + b_{s2}} + \frac{2 h_1^2}{b_{s1} + b_{s2}}) \quad (4-6)$$




Figure 4-1 Slot geometry

where

$$D_o = D_i + 2h_1 + 2h_2 \quad (4-7)$$

Similar expressions may be obtained for other slot geometries.

For a traditional rotating alternator, with same shape of slots as shown in Fig. 4-1, the leakage inductance of one slot is:

$$L_{s\sigma} = \mu_o W_1^2 l_{ef} \left(\frac{h_2}{3b_{s2}} + \frac{2h_1}{b_{s1} + b_{s2}} \right) \quad (4-8)$$

where l_{ef} is the length of slot.

Comparing Eq. (4-6) and (4-8), there are two additional terms—term 2 and term 4—in (4-6). The reason is that unlike a traditional rotating alternator, the slot length of a tubular alternator is not the same for different diameters in the slot.

4.2. Determination of the Magnetizing Inductance

Applying Ampere's Law to the path ABCDEFA in Fig. 4-2, with a primary coil current I_1 , we obtain:

$$\begin{aligned} H_{sch}(b) + H_{scv}(2h_2 + b_b) + H_{sp}(2h_1) + H_{gav}2(g + h_m) \\ + H_{pcv}(b_p) + H_{pch}(b) = F = W_1 I_1 \end{aligned} \quad (4-9)$$

In Fig. 4-2, the flux distribution is given. With the dimensions defined in (2-6)-(2-12) and applying the continuity of flux condition across the five set of cross-sections in Fig. 4-2, we have:

$$(\tau + g + h_m)(D_m + g) B_{gav} = \frac{1}{2} (\tau + b_t) D_s B_{sp} \quad (4-10)$$

$$\frac{1}{2} (\tau + b_t) D_s B_{sp} = b_t D_{t1} B_{scv} \quad (4-11)$$

$$b_t D_{t1} B_{scv} = b_t D_{t2} B_{sch} \quad (4-12)$$

$$(\tau + g + h_m)(D_m + g) B_{gav} = (\tau + 2g + 2h_m) D_{p2} B_{pcv} \quad (4-13)$$

$$(\tau + 2g + 2h_m) D_{p2} B_{pcv} = b_p D_{p1} B_{pch} \quad (4-14)$$

For a certain value of B_{gav} , the flux density in other parts of the magnetic loop of the linear alternator can be obtained from Eq. (4-10) through (4-14). The corresponding field intensities are obtained from the magnetization curve of the core material. For air:

$$H_{gav} = \frac{1}{\mu_o} B_{gav} \quad (4-15)$$

After the field intensities in every part of the magnetic loop have been found, the magnetomotive force F needed to maintain the value of B_{gav} could be calculated by Eq. (4-9). The flux linkage, λ_m , is given by:

$$\lambda_m = W_1 \phi = W_1 B_{gav} \pi (D_m + g)(\tau + g + h_m) \quad (4-16)$$

Hence, the magnetizing inductance, L_m , may be expressed as:

$$L_m(I_1) = \frac{\lambda_m}{I_1} = \frac{W_1^2 B_{gav} \pi (D_m + g)(\tau + g + h_m)}{F} \quad (4-17)$$




Figure 4-2 Flux path and continuity of flux.

Notice that this inductance is a function of the primary current I_1 . Thus, the effect of core saturation is taken into account globally and L_m depends on the value of B_{gap} . Fig. 4-3 shows the variation of the L_m with B_{gap} in a tubular linear alternator.

4.3. The Equivalent Magnetizing Inductance of PM Linear Alternator

The method discussed in the preceding section is useful in finding the magnetizing inductance of a tubular linear alternator, such as self-excited, reluctance as well as the PM type. But for a PM linear alternator, the magnet's working point changes with the variation of load. Thus, the induced voltage will be reduced not only by the current reaction but also by the variation of the working point of the magnet when the load increases. For design and analysis of PM alternators, sometime it is convenient to define an equivalent magnetizing inductance as follows:

$$L_{me}(I_1) = \frac{E_o - E}{\omega I_1 \sin \theta} \quad (4-18)$$

where

E_o = no load induced voltage

E = airgap induced voltage corresponding to stator current I_1 and angle θ shown in Fig. 4-4.

ω = electrical angular frequency.

Now, the equation of circuit of Fig. 4-4 is:

$$\bar{E}_o = j\omega L_{me} \bar{I}_1 + j\omega L_{so} \bar{I}_1 + R_s \bar{I}_1 + \bar{V} \quad (4-19)$$

Consequently, $L_{me}(I_1)$ is called *an equivalent magnetizing inductance*.

4.4. Resistance of Stator Winding

The resistance of stator winding is given by:

$$R_s = \frac{\rho}{A_c} W_1 \pi (D_i + 2h_1 + h_2) \quad (4-20)$$

where

ρ = the resistivity of stator winding material

A_c = cross-section of stator winding wires

$D_i + 2h_1 + h_2$ = average diameter of stator winding

W_1 = turns of stator winding

4.5 An Example

For the PM tubular linear alternator, with the dimensions given in section 2.5, the leakage inductance of the slot is:

$$\begin{aligned} L_{so} &= \pi W_1^2 \mu_o \left[\frac{(D_i + 2h_1 + 2h_2)h_2}{3 b_{s2}} - \frac{h_2^2}{2 b_{s2}} + \frac{2D_i h_1}{b_{s1} + b_{s2}} + \frac{2h_1^2}{b_{s1} + b_{s2}} \right] \\ &= \pi \times 21^2 \times 1.26 \times 10^{-6} \left[\frac{(11 + 2 \times 0.2 + 2 \times 0.8) \times 0.8}{3 \times 3.44} - \frac{0.8^2}{2 \times 3.44} \right] \end{aligned}$$




Figure 4-3 The magnetizing inductance versus flux density




Figure 4-4 Phase diagram of a single phase alternator.

$$= + \frac{2 \times 11 \times 0.2}{2.04 + 3.44} + \frac{2 \times 0.2^2}{2.04 + 3.44} \Big] \times 0.0255$$
$$= 0.0771 \text{ mH}$$

For $I_1 = 210 \text{ A}$ and $\theta = 45^\circ$:

Using the method introduced in section 4.2, the magnetizing inductance is:

$$L_m = 0.822 \text{ mH}$$

By the definition given in Section 4.3, the equivalent magnetizing inductance is:

$$L_{me} = 0.832 \text{ mH}$$

The constant k , which is calculated by (3-18), is:

$$k = 0.3738 \times 10^{-7} \text{ Wb m/A turn}$$

From this example, it can be seen that the value of L_m is close to that of L_{me} . But if k is much larger than the above value for designed alternator, the difference between L_m and L_{me} will be large.

CHAPTER 5

DESIGN OF A TUBULAR PM LINEAR ALTERNATOR

In Reference 5, the basic design guide of PM linear alternators with tuning capacitor is given. The design procedure of PM linear alternators *without tuning capacitor* is presented as follows with a design example. The configuration and dimension symbols of the designed alternator are the same as those shown in Fig. 2-1.

5.1. Given Data

Rated output power (s) = 25 kVA

Frequency (f_m) = 100 Hz

Plunger travel length (ℓ_{stroke}) = 1.0 inch

Assumptions and Estimates

Length of pole shoe of stator $\tau = 1.2$ in

Pole length of plunger, $\tau_m = 1.0$ in

Airgap $g = 0.036$ in

Full-load output voltage $V = 120$ V (rms)

Induced (or internal) voltage $E = \sqrt{2}(120)$ V (rms)

Maximum induced voltage $E_m = 2(120) = 240$ V (max)

Output current $I = \frac{S}{V} = \frac{25000}{120} = 208.33$ A

Magnet material = Tascore 27 H $B_r = 1.07$ T, $H_c = 770.305$ KA/m

5.3. Design Procedure

Let $B_m = 0.97$ T (satisfied after iterations)

$$H_m = H_c \left(1 - \frac{B_m}{B_r}\right) = -770.305 \left(1 - \frac{0.97}{1.07}\right) = -71.99 \text{ kA/m} \quad (5-1)$$

$$B_{gav} = \frac{B_m \tau_m}{\frac{1}{2} (\tau_m + \tau) K_{\sigma m}} = \frac{0.97 \times 1}{1.1 \times 1.05} = 0.7688 \text{ T} \quad (5-2)$$

where $k_{\sigma m}$ = leakage coefficient = 1.05 (assumed)

$$H_m h_m = \frac{B_{gav}}{\mu_o} g k_s = H_{gav} g k_s \quad (5-3)$$

where k_s = no-load saturation factor = 1.5 (assumed)

From (5-3):

$$h_m = \frac{B_{gav}}{\mu_o H_m} g k_s = \frac{0.7688 \times 0.036 \times 0.0254 \times 1.5}{1.26 \times 10^{-6} \times 71.99 \times 10^3} = 0.456 \text{ in}$$

The emf equation is:

$$E_m = B_{gap} W_1 \omega_r \ell_{stroke} \pi D_i \quad (5-4)$$

where W_1 is the number of turns on stator. Thus, from (5-4) with $W_1 = 21$ turns.

$$\begin{aligned} D_i &= \frac{E_m}{\pi B_{gap} W_1 \omega_r \ell_{stroke}} = \frac{240}{\pi \times 0.7668 \times 21 \times 628 \times 1 \times 0.0254} \\ &= 0.2963 \text{ m} = 11.62 \text{ in} \end{aligned} \quad (5-5)$$

5.4. Summary of Design Data

$$D_i = 11 \text{ in} = 0.2805 \text{ m}$$

$$h_m = 0.46 \text{ in}$$

$$g = 0.036 \text{ in}$$

$$\tau = 1.2 \text{ in}$$

$$\tau_m = 1 \text{ in}$$

$$g_m = \tau - \tau_m = 0.2 \text{ in}$$

5.5. Further Calculations

$$\begin{aligned} K &= \left\{ \frac{\pi}{g_m} \left[(D_i - 2g - h_m)h_m + \frac{4}{3} h_m^2 \right] + 2(D_i - 2g - h_m) \right. \\ &\quad \left. + (D_i - g - h_m) \ln \left(\frac{h_m + 2g}{h_m} \right) \right\} h_m \mu_o \end{aligned}$$

Leakage flux of permanent magnet is:

$$\phi_\sigma = -KH_m = -KH_c \left(1 - \frac{B_m}{B_r} \right) \quad (5-7)$$

The flux linking with the stator coil is:

$$\phi = \pi(D_i - 2g - h_m)\tau_m B_m - \phi_\sigma \quad (5-8)$$

which is related to the induced voltage by:

$$E = \sqrt{2} \pi W_1 f_m \phi \quad (5-9)$$

With the current density chosen as $J_{co} = 5 \text{ A/mm}^2$, the wire cross-section area is given by:

$$A_{co} = \frac{I}{J_{co}} = \frac{208.33}{5} = 41.66 \text{ mm}^2 = 0.0641 \text{ in}^2$$

To obtain this area of cross-section, 4 No. 7AWG wires, each having a diameter of 0.1443 in, may be used in parallel. Thus:

$$A_{co} = 4 \times \frac{\pi}{4} (0.1443 \times 25.5)^2 = 42.54 \text{ mm}^2$$

Let the slot fill-factor $k_{fu} = 0.5$. Then slot area:

$$A = \frac{W_1 A_{co}}{k_{fu}} = \frac{21 \times 42.54}{0.5} = 1786.68 \text{ mm}^2 = 2.75 \text{ in}^2 \quad (5-10)$$

Let $b_t = 0.5$ in, $b_b = 0.45$ in, $h_1 = 0.2$ in, $b_p = 0.7$ in, $h_2 = 0.8$ in, and $b_{s2} = 3.44$ in.

Then:

$$b_{s2} h_2 = 3.44 \times 0.8 = 2.753 \text{ in}^2 = A \quad (5-11)$$

which is adequate slot area.

By the computer calculation for above design, the following no-load data are obtained:

$$E = 169.505 \text{ V}$$

$$\phi = 0.01817 \text{ Wb}$$

$$k_{sm} = 1.1446$$

$$B_m = 0.9724 \text{ T}$$

$$H_m = -70.252 \text{ kA/m}$$

Average diameter of the winding:

$$D_{av} = D_i + 2h_1 + h_2 = 11 + 0.4 + 0.8 = 12.2 \text{ in} \quad (5-12)$$

Stator winding resistance:

$$R_s = \rho \frac{W_1 \pi D_{av}}{A_{co}} = 2.1 \times 10^{-8} \frac{21 \times \pi \times 12.2 \times 0.0254}{42.54 \times 10^{-6}} = 0.0103 \Omega \quad (5-13)$$

Stator leakage inductance:

$$\begin{aligned} L_\sigma &= \mu_o \pi W_1^2 \left[\frac{(D_i + 2h_1 + 2h_2)h_2}{3b_{s2}} + \frac{2D_i h_1}{b_{s1} + b_{s2}} - \frac{h_2^2}{2b_{s2}} + \frac{2h_1^2}{b_{s1} + b_{s2}} \right] \\ &= 1.26 \times 10^{-8} \times \pi \times 21^2 \left[\frac{13 \times 0.8}{3 \times 3.44} + \frac{2 \times 11 \times 0.2}{2.04 + 3.44} - \frac{0.8^2}{2 \times 3.44} + \frac{2 \times 0.2^2}{2.04 + 3.44} \right] \times 0.0254 \\ &= 0.0771 \text{ mH} \end{aligned} \quad (5-14)$$

For $I = 208.33 \text{ A}$ and $\theta = 45^\circ$, equivalent magnetizing inductance $L_{me} = 0.832 \text{ mH}$, as calculated by computer. This inductance accounts for armature reaction as well as the effect of change of the magnet leakage flux. Hence, the total synchronous reactance of the linear alternator becomes:

$$\begin{aligned} X_s &= \omega_r (L_{me} + L_\sigma) = 628(0.832 + 0.0771) \times 10^{-3} \\ &= 0.5709 \Omega \end{aligned} \quad (5-15)$$

5.6. Maximum Power Condition

Suppose that the load of the linear alternator is purely resistive and armature resistance is negligible, the phasor diagram of the linear alternator is shown in Fig. 5-1.

$$\text{Output power: } S = VI \quad (5-16)$$

From Fig. 5-1,

$$I X_s = E \sin \theta \quad (5-17)$$

or

$$I = \frac{E}{X_s} \sin \theta \quad (5-18)$$

And

$$V = E \cos \theta \quad (5-19)$$

Thus,

$$S = \frac{E^2}{X_s} \sin \theta \cos \theta = \frac{E^2}{2X_s} \sin 2\theta \quad (5-20)$$

which is maximum when $2\theta = 90^\circ$ or $\theta = 45^\circ$. Under this condition,

$$I = \frac{E}{\sqrt{2} X_s} = \frac{169.505}{\sqrt{2} \times 0.5709} = 209.95 \text{ A} \quad (5-21)$$

$$\text{Rated Load: } R_L = X_s - R_a = 0.5709 - 0.0101 = 0.5608 \Omega$$

$$\text{Output Voltage: } V = I R_L = 209.95 \times 0.5608 = 117.74 \text{ V}$$

$$\text{Output kVA} = 117.74 \times 209.95 \times 10^{-3} = 24.72 \text{ kVA}$$

5.7. Weight-to-Power Ratio

$$\begin{aligned} (Vol)_{\text{stator}} &= \frac{\pi}{4} \left[(D_i + 2h_1 + 2h_2 + 2b_b)^2 - (D_i + 2h_1 + 2h_2)^2 \right] (2b_t + b_{s2}) \\ &\quad + \frac{\pi}{4} \left[(D_i + 2h_1 + 2h_2)^2 - (D_i + 2h_1)^2 \right] 2b_t \\ &\quad + \frac{2\pi}{4} \left[(D_i + 2h) - D_i^2 \right] \left[\frac{1}{2} (b_t + r) \right] \\ &= \frac{\pi}{4} (13.9^2 - 13^2) \times 3.54 + \frac{\pi}{4} (13^2 - 11.4^2) \times 1.0 + \frac{\pi}{4} (11.4^2 - 11^2) \times 0.85 \\ &= 109.936 \text{ in}^3 = 0.001823 \text{ m}^3 \end{aligned} \quad (5-25)$$

$$\begin{aligned} (Vol)_{\text{magnet}} &= 4 \left[(D_i - 2g)^2 - (D_i - 2g - 2h_m)^2 \right] \frac{\pi}{4} \tau_m \\ &= (10.94^2 - 10.02^2) \times \pi \times 1 \\ &= 60.58 \text{ in}^3 = 0.001005 \text{ m}^3 \end{aligned} \quad (5-26)$$




Figure 5-1 Phasor diagram of the alternator.

$$\begin{aligned}
 (Vol)_{plunger} &= \frac{\pi}{4} \left[(D_i - 2g - 2h_m)^2 - (D_i - 2g - 2h_m - 2b_p)^2 \right] (b_{e2} + 2\tau) \\
 &= \frac{\pi}{4} (10.02^2 - 8.62)^2 (3.44 + 2.4) \\
 &= 119.695 \text{ in}^3 = 0.001985 \text{ m}^3
 \end{aligned} \tag{5-27}$$

$$\begin{aligned}
 (Vol)_{copper} &= \pi D_{av} A_{co} W_i \\
 &= \pi \times 12.2 \times 0.06542 \times 21 = 52.655 \text{ in}^3 = 0.000873 \text{ m}^3
 \end{aligned} \tag{5-28}$$

Assuming a mean mass density of $7.8 \times 10^3 \text{ kg/m}^3$, the total weight of the linear alternator becomes:

$$\begin{aligned}
 W &= (0.001823 + 0.001005 + 0.001985 + 0.000873) \times 7.8 \times 10^3 \\
 &= 44.3508 \text{ kg} = 97.572 \text{ lb.}
 \end{aligned} \tag{5-29}$$

$$\frac{\text{weight}}{\text{power}} = \frac{44.3808}{24.72} = 1.794 \text{ kg/kW} = 3.947 \text{ lb/kW} \tag{5-30}$$

5.8. Losses and Electrical Efficiency

Copper loss:

$$I^2 R_a = 209.95^2 \times 0.0101 = 445.198 \text{ W} \tag{5-31}$$

Core loss:

First we determine the weight of iron:

$$\begin{aligned}
 W_{ep} &= 2 \times \frac{\pi}{4} \left[(D_i + h_1)^2 - D_i^2 \right] \frac{1}{2} (b_t + \tau) \times 7.8 \times 0.254^3 \\
 &= 1.5473 \text{ kg} = 3.404 \text{ lb}
 \end{aligned} \tag{5-32}$$

$$\begin{aligned}
 W_{ev} &= \frac{\pi}{4} \left[(D_i + 2h_1 + 2h_2)^2 - (D_i + 2h_1)^2 \right] 2b_t \times 7.8 \times 0.254^3 \\
 &= 3.9656 \text{ kg} = 8.724 \text{ lb}
 \end{aligned} \tag{5-33}$$

$$\begin{aligned}
 W_{ech} &= \frac{\pi}{4} \left[(D_i + 2h_1 + 2h_2 + 2b_p)^2 - \right. \\
 &\quad \left. - (D_i + 2h_1 + 2h_2)^2 \right] (b_{e2} + 2b_t) \times 7.8 \times 0.254^3 \\
 &= 8.7056 \text{ kg} = 19.153 \text{ lb}
 \end{aligned} \tag{5-34}$$

$$W_p = 1.985 \times 7.8 = 15.483 \text{ kg} = 34.063 \text{ lb} \tag{5-35}$$

From the flux density of every part of iron and core loss curve shown in Fig. 5-2, the core loss coefficients are found as follows:

$$C_{ep} = 0.304 \left(\frac{100}{60} \right)^{1.3}, C_{ev} = 0.587 \left(\frac{100}{60} \right)^{1.3}, C_{ech} = 0.609 \left(\frac{100}{60} \right)^{1.3} \text{ and } C_p = 0.957 \left(\frac{100}{60} \right)^{1.3}$$




Figure 5-2 Core loss and exciting VA for M-19 steel at 60 Hz.

The corresponding losses are:

$$(loss)_{ep} = W_{ep} C_{ep} = 3.404 \times 0.304 \left(\frac{100}{60} \right)^{1.3} = 2.0103 \text{ W} \quad (5-36)$$

$$(loss)_{ev} = W_{ev} C_{ev} = 8.724 \times 0.587 \left(\frac{100}{60} \right)^{1.3} = 9.949 \text{ W} \quad (5-37)$$

$$(loss)_{eh} = W_{eh} C_{eh} = 19.153 \times 0.609 \left(\frac{100}{60} \right)^{1.3} = 22.66 \text{ W} \quad (5-38)$$

$$(loss)_p = W_p C_p = 34.063 \times 0.957 \left(\frac{100}{60} \right)^{1.3} = 63.329 \text{ W} \quad (5-39)$$

$$\begin{aligned} (loss)_{total \text{ core}} &= (loss)_{ep} + (loss)_{ev} + (loss)_{eh} + (loss)_p \\ &= 97.948 \text{ W} \end{aligned} \quad (5-40)$$

$$\text{copper loss} + \text{core loss} = 445.198 + 97.948 = 543.146 \text{ W} \quad (5-41)$$

$$\begin{aligned} \text{Electrical efficiency} &= \frac{\text{output}}{\text{output} + \text{losses}} \\ &= \frac{24.72}{24.72 + 0.543} = 97.85\% \end{aligned} \quad (5-42)$$

CHAPTER 6

OPTIMAL DESIGN OF A PM LINEAR ALTERNATOR

6.1. Concept of Optimal Design

For a specified rating (kVA) and output voltage (or current), a PM linear alternator can have numerous possible shapes and dimensions. The objective of optimal design is to design the machine which has the best pre-determined characteristics and satisfies specified constraints such as output voltage and alternator rating. In our design, we will attempt to achieve a minimum power-to-weight ratio and a maximum electrical efficiency by applying a mathematical optimization technique.

In an optimal design, we choose design variables and an objective function, which is a function of design variables and describes the characteristics to be optimized. We then find the set of values of the design variables, which correspond to the maximum or minimum value of the objective function with some equality or inequality constraints, which are the required conditions that the design must satisfy. Mathematically, the optimization problem may be stated as follows:

For the design variables $x_1, x_2, \dots, x_n = X$, find

$$\min F = f(x_1, x_2, \dots, x_n) = f(X) \quad (6-1)$$

subject to:

$$g_j(X) \leq 0 \quad j = 1, 2, \dots, J \quad (6-2)$$

$$h_k(X) = 0 \quad k = 1, 2, \dots, K \quad (6-3)$$

6.2. Penalty Function Methods

The penalty function methods convert a constrained optimization problem into an unconstrained optimization problem. These methods are algorithms which generate a sequence of points from $X^{(0)}$ to $X^{(T)}$, where $X^{(0)}$ is the initial point, $X^{(t)}$ the generic point and $X^{(T)}$ the limit point, and the best estimate of the optimal point X^* is produced by the algorithm. The points $X^{(t)}$, $t=1, 2, \dots, T$ are stationary points of the penalty function.

Consider the penalty function:

$$P(X, R) = f(X) + \Omega[R, g(X), h(X)] \quad (6-4)$$

where R is a set of penalty parameters, and Ω the penalty term. Then $P(X, R)$ is a function of R and the constraint functions. Penalty function methods are classified according to the procedure employed for handling inequality constraints. These methods are referred to as interior or exterior point method according as the sequence $X^{(t)}$ contains feasible or infeasible points, respectively. If the sequence of stationary point contains both feasible and infeasible points, the method is said to be mixed.

The interior penalty function technique arguments the objective function with a penalty term which is small at points away from the constraints in the feasible

region, but which "blow up" as the constraints are approached.

The penalty function is of the form:

$$P(F, R_t) = f(X^{(t)}) - \sum_{j=1}^J \frac{R_t}{g_j[X^{(t)}]} + \frac{1}{\sqrt{R_t}} \sum_{k=1}^K h_k [X^{(t)}]^2 \quad (6-5)$$

with $R_1 > R_2 > \dots > R_t > R_{t+1} > \dots > 0$

and $\lim_{t \rightarrow \infty} R_t = 0$

Therefore, when $t \rightarrow \infty$, $\frac{1}{\sqrt{R_t}} \rightarrow \infty$, and it forces $h_k [X^{(t)}]^2$, $k=1,2,\dots,K$, approach zero, when minimum of $P(F, R_t)$ is approached. Inequality constraints are satisfied since $X^{(t)}$, $t=1,2,\dots,T$, are feasible points of inequality constraints. When $t \rightarrow \infty$, $P(F, R_t)$ has the same external as $F = f(X)$ has.

The exterior penalty function technique modifies the objective function by adding a penalty whenever a constraint is violated. The penalty function takes the form:

$$P(F, R_t) = f[X^{(t)}] + R_t \sum_{j=1}^J \langle g_j[X^{(t)}] \rangle^2 + \sum_{k=1}^K h_k [X^{(t)}]^2 \quad (6-6)$$

with $0 < R_1 < R_2 < \dots < R_t < R_{t+1} < \dots$

$\lim_{t \rightarrow \infty} R_t = +\infty$

and

$$\langle g_i[X^{(t)}] \rangle = \begin{cases} 0 & \text{if } g_i[X^{(t)}] \leq 0 \\ g_i[X^{(t)}] & \text{if } g_i[X^{(t)}] > 0 \end{cases}$$

With t increasing, the minimum of $P(F, R_t)$ will conjugate to the minimum of $F = f(X)$ and the constraints of $g_j(X)$ will be satisfied for $j=1,2,\dots,J$. Also the $h_k [X^{(t)}]^2$ will be forced to approach zero when a minimum of $P(F, R_t)$ is approached for $k=1,2,\dots,K$.

6.3. Optimal Design of PM Linear Alternator

For the PM linear alternator shown in Fig. 2-1, we choose: $\tau_m = 1.0$ in, $h_1 = 0.2$ in. Let: $X_1 = g$; $X_2 = h_m$; $X_3 = D_i$; $X_4 = r$; $X_5 = b_b$; $X_6 = b_p$; $X_7 = h_2$; $X_8 = b_{r2}$; $X_9 = W_1$ (number of turns of the coil); and $X_{10} = b_t$ are the design variables, which change during the optimization procedure. Other dimensions can be obtained from τ_m , h_1 and the design variables. The cross-section of the wire used for the coil is given by:

$$A_{co} = \frac{h_2 b_{r2} k_{fu}}{W_1} \quad (6-7)$$

where k_{fu} is the slot fill factor = 0.5 (assumed).

The objective function in this design is the sum of the ratio of weight to output power (lb/kVA) and the ratio of iron and copper losses to output power, i.e.:

$$F = \frac{W}{S} + \frac{Z_i + Z_c}{1000S} \quad (6-8)$$

where W - weight in lb; S = kVA rating; Z_i = iron loss in watts; and Z_c = copper loss in watts.

The goal of the optimal design is to find a set of design variables which make F a minimum and satisfy the following constraints:

output power $S = 25 \text{ kVA}$

output voltage $V \leq 500 \text{ V}$

current density $J_c \leq 5 \text{ A/mm}^2$

pole shoe length $\tau \leq 1.2 \text{ in}$

airgap $g \geq 0.03 \text{ in}$

The optimization subroutine package OPTLIB was used to obtain the optimal design, and the method used is the exterior penalty function. So, the optimal design problem reduces to obtaining the design variables which correspond to the minimum value of an unconstrained function $P(F,R)$, which is a function of F and the above constraints. The algorithm of optimal design is as follows:

- (i) Choose initial values of design variables.
- (ii) Calculate no-load electromagnetic field, no-load induced voltage E_o , coil resistance R_s and leakage inductance L_{oo} .
- (iii) Calculate electromagnetic field corresponding to $\theta = 45^\circ$ and purely resistive load. Find the induced voltage drop due to armature reaction and the working point variation of the permanent magnet. Then find the equivalent mutual inductance L_{me} , output voltage V , stator current I_1 , output power S , weight W and the losses Z_i and Z_c .
- (iv) Check if $P(F,R)$ has a minimum value and satisfies accuracy
yes: Go to (vi)
no: Go to (v)
- (v) Find new search direction and new design variables, go to step 2.
- (vi) Stop.

The flow chart of optimal design is shown in Fig. 6-1.

The initial values of the design variables were chosen as follows:

$$x_1 = g = 0.03 \text{ in}$$

$$x_2 = h_m = 0.4 \text{ in}$$

$$x_3 = D_i = 16.0 \text{ in}$$

$$x_4 = \tau = 1.1 \text{ in}$$

$$x_5 = b_b = 0.8 \text{ in}$$

$$x_6 = b_p = 0.8 \text{ in}$$


$$x_7 = h_2 = 2.0 \text{ in}$$

$$x_8 = b_{s2} = 3.5 \text{ in}$$

$$x_9 = W_1 = 21 \text{ turns}$$

$$x_{10} = b_t = 0.8 \text{ in}$$

ORIGINAL PAGE IS
OF POOR QUALITY



ORIGINAL PAGE IS
OF POOR QUALITY

- 41 -

ORIGINAL PAGE IS
OF POOR QUALITY




Figure 6-1 Flow chart of optimal design.

The optimal values of the design variables are:

$$\begin{aligned}x_1 &= g = 0.031 \text{ in} \\x_2 &= h_m = 0.44 \text{ in} \\x_3 &= D_i = 11.35 \text{ in} \\x_4 &= \tau = 1.2 \text{ in} \\x_5 &= b_b = 0.34 \text{ in} \\x_6 &= b_p = 0.50 \text{ in} \\x_7 &= h_2 = 0.91 \text{ in} \\x_8 &= b_{s2} = 3.63 \text{ in} \\x_9 &= W_1 = 85 \text{ turns} \\x_{10} &= b_t = 0.38 \text{ in}\end{aligned}$$

From the design the following characteristics of the linear alternator are obtained:

No-load induced voltage, $E_o = 571.58$ Volt

Output voltage, $V = 395.26$ Volt

Stator current, $I_1 = 62.74$ A

Stator resistance, $R_s = 0.142 \Omega$

Stator leakage inductance, $L_{so} = 1.93$ mH

Stator mutual inductance, $L_m = 8.33$ mH

Cross-section of stator winding $A_{co} = 12.715 \text{ mm}^2$

Weight/power ratio, $\frac{W}{S} = 3.72 \text{ lb/kVA}$

Losses/output power $Z/1000S = 0.0233$

Output power, $S = 24.8 \text{ kVA}$.

Field of without load:

$B_m =$	0.89039 T	$H_m =$	-129306.30000 A/m
$B_{sp} =$	0.81040 T	$H_{sp} =$	66.29997 A/m
$B_{scv} =$	1.51587 T	$H_{scv} =$	2588.85600 A/m
$B_{sch} =$	1.58820 T	$H_{sch} =$	3974.03300 A/m
$B_{pcv} =$	0.95107 T	$H_{pcv} =$	83.88339 A/m
$B_{pch} =$	1.94321 T	$H_{pch} =$	15728.46000 A/m

Field for $I_1 = 62.74$ A and $\theta = 45^\circ$

$B_m =$	0.82138 T	$H_m =$	-178987.50000 A/m
$B_{sp} =$	0.48215 T	$H_{sp} =$	38.75073 A/m
$B_{scv} =$	0.90188 T	$H_{scv} =$	77.73460 A/m
$B_{sch} =$	0.94491 T	$H_{sch} =$	83.11403 A/m
$B_{pcv} =$	0.73906 T	$H_{pcv} =$	59.51506 A/m
$B_{pch} =$	1.51003 T	$H_{pch} =$	2477.14200 A/m

CHAPTER 7

CONCLUSIONS

In the preceding chapters certain important aspects of analysis, design and optimal design of single-phase single-slot tubular PM linear alternators have been investigated.

Methods developed in Chapters 2 and 3 are used to find the mutual magnetic field in every section of the linear alternator and the leakage magnetic field, with load or without load. Furthermore, the induced voltage may be obtained from the magnetic field, if the stator winding turns and frequency of the alternator are known.

The field of every section of the alternator, found by the methods developed in Chapter 2 and 3, is the average value of the field. However, it is good enough for finding the induced voltage. The advantage of these methods is that they make the calculation of the alternator's field much more easy and simple than by numerical method. The simplicity is significant for the optimal design of the alternators.

The methods and formulas presented in Chapter 4 are available for finding the parameters of the alternators, which are necessary for transient state and steady state analysis of the alternators.

The procedure discussed in Chapter 5 is the essential design guideline of tubular PM linear alternators. Combining the design guideline in Chapter 5 and mathematical optimization method, the technique presented in Chapter 6 ensures that the designed alternator has best specialized characteristics, which is defined by the optimal function, as shown in the design example.

The methods and formulas presented in this report and in reference [4] and [5] form the essential knowledge for analysis, design and operation of PM linear alternators.

REFERENCES

1. Roters, H. C., "Compensated reciprocating electrodynamic machine," US Patent 3,891,874, 1975.
2. Bhate, S. K., "Linear oscillating electric machine with permanent magnet excitation," US Patent 4,349,787, 1982.
3. Redlish, R. W., "Electromechanical transducer particularly suitable for a linear alternator driven by a free-piston Stirling engine," US Patent, 4,602,174, 1986.
4. Boldea, I. and Nasar, S. A., "Permanent magnet linear alternator: Part I fundamental equations," *IEEE Trans.*, Vol. AES-23, Jan 1987, pp. 73-78.
5. Boldea, I. and Nasar, S. A., "Permanent magnet linear alternator: Part II basic design guidelines," *IEEE Trans.*, Vol. AES-23, Jan 1987, pp. 79-82.
6. NASA Lewis Research (private communication).

APPENDIX I

215		H0=0.5*HC	CE 00
216	10	CONTINUE	CE 00
217		BM=BR*(1.0-H0/HC)	CE 00
218		QL=-AK*H0	CE 00
219		Q=PI*(DI-2.0*GG-HSM)*TM*BM-QL	CE 00
220		BSP=Q/SSP	CE 00
221		BSCV=Q/SSCV	CE 00
222		BSCH=Q/SSCH	CE 00
223		BPCV=(Q+QL)/SPCV	CE 00
224		BPCH=(Q+QL)/SPCH	CE 00
225		CALL BH(BSP,HSP)	CE 00
226		CALL BH(BSCV,HSCV)	CE 00
227		CALL BH(BSCH,HSCH)	CE 00
228		CALL BH(BPCV,HPCV)	CE 00
229		CALL BH(BPCH,HPCH)	CE 00
230		BGAV=Q/SG1	CE 00
231		HGAV=BGAV/U0	CE 00
232		FM=HSCH*B+HSCV*(2.0*H2+BB)+HSP*2.0*H1+HPCV*BP+HPCH*B+HGAV*2.0*GG	CE 00
233		HM=-FM/2.0/HSM	CE 00
234		IF (ABS(HM-H0).LT.1.0) GO TO 50	CE 00
235		H0=0.5*(HM+H0)	CE 00
236		GO TO 10	CE 00
237	50	HM=0.5*(HM+H0)	CE 00
238		BM=BR-BR/HC*HM	CE 00
239		AKM=(Q-AK*HM)/Q	CE 00
240		E0=SQRT(2.0)*PI*W1*FME*Q	CE 00
241		AS=H2*BS2	ODL00
242		AW=0.5*AS/W1	ODL00
243		RA=2.1E-8*W1*PI*(DI+2.0*H1+H2)/AW	ODL00
244		BS=0.5*(BS1+BS2)	ODL00
245		ALL=PI*W1**2*U0*((DI+2.0*(H1+H2))*H2/3.0/BS2-H2**2/2.0/BS2+ * 2.0*(DI+H1)*H1/BS)	ODL00
246		AIN=1.0E6*AW*5.0	ODL00
247		AI0=AIN	ODL00
248		D=1.0-AK*HC/BR/SG3M	DE 00
249		D1=BR*SG3M*GG/SG1	DE 00
250		D2=SG3M*GG/SG1/SG3	DE 00
251		A=-D1/((GG+HSM)/SG2+D2-GG/SG11)	DE 00
252		C=(-U0*HSM+D1/HC*D)/((GG+HSM)/SG2+D2-GG/SG11)	DE 00
253	105	AIF=AI0/SQRT(2.0)	DE 00
254		H0=0.5*HC	DE 00
255	110	CONTINUE	DE 00
256		Q2=A+C*H0	DE 00
257		Q1=((HC-D*H0)*BR/HC+Q2/SG3)*SG3M	DE 00
258		Q=Q1-Q2	DE 00
259		BSP=Q/SSP	DE 00
260		BSCV=Q/SSCV	DE 00
261		BSCH=Q/SSCH	DE 00
262		BPCV=(Q1-AK*H0-Q2)/SPCV	DE 00
263		BPCH=(Q1-AK*H0-Q2)/SPCH	DE 00
264		CALL BH(BSP,HSP)	DE 00
265		CALL BH(BSCV,HSCV)	DE 00
266		CALL BH(BSCH,HSCH)	DE 00
267		CALL BH(BPCV,HPCV)	DE 00
268		CALL BH(BPCH,HPCH)	DE 00
269		FM=HSCH*B+HSCV*(2.0*H2+BB)+HSP*2.0*H1+HPCV*BP+HPCH*B	DE 00
270		HM=((Q2/(Q1-Q2)*FM+W1*AIF)*SG2*U0/2.0/(GG+HSM)-A)/C	DE 00
271		IF (ABS(HM-H0).LT.1.0) GO TO 150	DE 00

272	H0=0.5*(HM+H0)	DE 00
273	GO TO 110	DE 00
1 274	150 HM=0.5*(HM+H0)	DE 00
275	BM=BR-BR/HC*HM	DE 00
276	Q2=A+C*HM	DE 00
277	Q1=((HC-D*HM)*BR/HC+Q2/SG3)*SG3M	DE 00
278	Q=Q1-Q2	DE 00
279	AKM=(Q1-AK*HM)/Q1	DE 00
280	E=SQRT(2.0)*PI*W1*FME*Q	DE 00
281	AL=(E0-E)/AIF/628.0	DE 00
282	AI=E0/SQRT(2.0)/(AL+ALL)/628.0	DE 00
283	IF (ABS((AI-AI0)/AI0).LT.0.03) GO TO 152	DE 00
284	AI0=0.5*(AI+AI0)	DE 00
285	GO TO 105	DE 00
286	152 CONTINUE	DE 00
	C	ODL00
287	D1=DI+2.0*(H1+H2+BB)	ODL00
288	D2=DI+2.0*(H1+H2)	ODL00
289	D3=DI+2.0*H1	ODL00
290	D4=DI-2.0*GG	ODL00
291	D5=DI-2.0*(GG+HSM)	ODL00
292	D6=DI-2.0*(GG+HSM+BP)	ODL00
293	V1=PI/4.0*(D1**2-D2**2)*(BS2+2.0*BT)	ODL00
294	V2=PI/4.0*(D2**2-D3**2)*2.0*BT	ODL00
295	V3=PI/4.0*(D3**2-DI**2)*0.5*(BT+T)*2.0	ODL00
296	VS=V1+V2+V3	ODL00
297	VM=PI*(D4**2-D5**2)*TM	ODL00
298	VP=PI/4.0*(D5**2-D6**2)*(BS2+2.0*T)	ODL00
299	VC=PI*(DI+2.0*H1+H2)*AW*W1	ODL00
300	W=7.8*(VS+VM+VP+VC)*1000.0*2.2	ODL00
301	V=E0/SQRT(2.0)-AI*RA	ODL00
302	S=V*AI	ODL00
303	ZC=AI**2*RA	ODL00
304	CALL CL(BSCH,FSCH)	ODL00
305	CALL CL(BSCV,FSCV)	ODL00
306	CALL CL(BSP,FSP)	ODL00
307	CALL CL(BPCH,FPCH)	ODL00
308	FRA=(100.0/60.0)**1.3	ODL00
309	ZSCH=2200.0*V1*FSCH*FRA	ODL00
310	ZSCV=2200.0*V2*FSCV*FRA	ODL00
311	ZSP=2200.0*V3*FSP*FRA	ODL00
312	ZP=2200.0*VP*FPCH*FRA	ODL00
313	ZR=ZSCH+ZSCV+ZSP+ZP	ODL00
314	Z=ZC+ZR	ODL00
315	F=(1000.0*W+Z)/S*10.0	ODL00
316	G(6)=(25000.0-S)/25000.0	ODL01
317	G(3)=(AI-AIN)/10.0	ODL01
318	G(2)=(0.3-X(1))*100.	ODL01
319	G(1)=(X(4)-0.12)*10.	ODL01
320	G(4)=(1.6*RR-BS1)*10	ODL01
321	G(5)=V-500.0	ODL01
322	UF=F	ODL01
323	RETURN	ODL01
324	END	ODL01
	C	ODL01
325	SUBROUTINE GRADU(X,S,SUM)	ODL01
326	RETURN	ODL01
327	END	ODL01
	C	ODL01
328	SUBROUTINE CL(B,F)	ODL01

